



GNSS Firmware v5.7

Release Notes

December 2025

©Copyright Topcon Positioning Systems, Inc. 2025.

All contents in this document are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

Table of Contents

SUPPORTED PRODUCTS.....	3
SYSTEMS	3
OEM	3
ACCOMPANYING TOPCON SOFTWARE AND FIRMWARE.....	3
FEATURES AND CHANGES	3
GENERAL.....	3
FIXED ISSUES	3

Supported Products

Systems

- Topcon NET-G5, HiPer HR, HiPer VR, HiPer CR, MM-2, MR-2, GR-5+
- Sokkia GNR5, GRX3, GCX3

OEM

- Topcon B111, B111A, B125, B210, B310

Accompanying Topcon Software and Firmware

- To access all new features and improved functionality available in GNSS Firmware 5.7 or later, the following Topcon software versions (or later) are recommended:
 - TRU v4.1
 - Topcon Field and Office v10.0
 - Pocket 3D v15.5.2
- BLE Firmware v1.8 (HiPer VR, GRX3)

Features and Changes

General

- Updated cybersecurity features. Note: To access the new cybersecurity features, FW 5.7 must be used; previous firmware versions have reduced cybersecurity capabilities.
- FTP is disabled by default to improve system security
- TCP connections now require a strong password before activation
- mmGPS improvements
- Optimized PPP, RTK and VHD algorithms
- Improved RTK performance, including long baselines and high ionosphere conditions
- Enhanced dual-frequency (L1/L5) processing
- Galileo HAS optimizations for Skybridge usage
- GNSS spectrum visualization
- TILT/HIMU updates for World Magnetic Model 2025
- Antenna calibration and database updates
- General improvements to stability, tracking, and positioning

Fixed Issues

- Improved robustness when satellite sets change during PPP operation
- Improved startup stability for network receivers
- Improved storing of data in NVRAM including instances where non-permanent parameters had previously not been cleared
- Improved NAND block checksum handling in bootloaders

- Improved SD card logging reliability and internal media handling
- Increased robustness of data output over USB for long message sequence
- Fixed rare instance of receiver unresponsiveness after restart
- Fixed issue with VPN status
- Fixed NET-G5 Bluetooth issue related to EXT2 power reading
- Fixed multiple data output, logging, and file-handling issues
- Fixed cell FW version output for boards with previous EEPROM
- Fixed printing error for previous ARP coordinates in Autoseed DB
- Fixed issue with response on non-existent DDNS GRIL command
- Fixed GALILEO INAV in RINEX output
- Fixed L1C/B code measurements offset
- Fixed typo in TCP connection prompt for HiPer VR receiver
- Fixed user ID length to support 36 symbols
- Fixed VHD issues with number of used satellites
- Implemented a 3-second delay on FTP and TCP servers when an incorrect password is entered
- Imposed a minimum value of RMS values in NMEA GST message to avoid outputting zeroes
- Included information about GAL, BDS, QZSS in positioning to [NP] and [SC]
- Included information about PPP solution to [SC] in SkyBridge Mode