



# GNSS Firmware v4.7p10

---

## Release Notes

**March 2019**

©Copyright Topcon Positioning Systems, Inc. 2019.

All contents in this document are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

**Table of Contents**

**SUPPORTED PRODUCTS ..... 3**  
    SYSTEMS ..... 3  
    OEM BOARDS..... 3  
**FEATURES AND CHANGES ..... 3**

## Supported Products

### *Systems*

- Topcon HiPer SR, HiPer V, MC-i4, GR-5<sup>1</sup>, HiPer II, GRS-1, MC-i3<sup>2</sup>
- Sokkia GSX2, GRX2, GCX2, GRX1<sup>3</sup>, and GHX2 (Mesa RTK)

### *OEM Boards*

- B110

## Features and Changes

- Improved firmware performance during leap second and GPS week rollover events.

---

<sup>1</sup> GR-5 with Vanguard technology now supported by FW 5.1p1 and later.

<sup>2</sup> GR-5 (without Vanguard technology), HiPer II, GRS-1, and MC-i3 sales have been discontinued. Service and technical support is still available for these products.

<sup>3</sup> Sokkia GCX2 and GRX1 sales have been discontinued. Service and technical support is still available for this product.