



# GNSS Firmware v4.8p3

---

## Release Notes

**November 2022**

©Copyright Topcon Positioning Systems, Inc. 2022

All contents in this document are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

# Table of Contents

- SUPPORTED PRODUCTS ..... 3**
  - SYSTEMS ..... 3
  - OEM BOARDS..... 3
- FEATURES AND CHANGES ..... 3**

## Supported Products

### *Systems*

- Topcon HiPer SR, GR-5<sup>1</sup>, HiPer V<sup>2</sup>, HiPer II, GRS-1, Net-G3A, MR-1, MC-i3, and MC-i4
- Sokkia GSX2, GCX2<sup>3</sup>, GRX2, GRX1, and GHX2 (Mesa RTK)

### *OEM Boards*

- B110, OEM-1, Euro 112PII

## Features and Changes

- Updated antenna database
- Improved resynchronization after corruptions and data loss with incoming RTCM3 corrections

---

<sup>1</sup> GR-5 with Vanguard technology now supported by FW 5.1p1 and later.

<sup>2</sup> GR-5 (without Vanguard technology), HiPer II, HiPer V, Net-G3A, MR-1, and GRS-1 sales have been discontinued. Service and technical support is still available for these products.

<sup>3</sup> Sokkia GRX1, GCX2, GRX2 sales have been discontinued. Service and technical support is still available for this product.